

Newsletter of The River Valley Flyers

Club #948

January 2020

President.....	Don Danczyk
Vice President/Secretary.....	Don Ryszka
Treasurer.....	Bob O'Connor
Safety Officer.....	Larry Chamberlin
Web Master.....	Bob O'Connor
Newsletter Editor.....	Don Danczyk
Indoor Flying Coordinator.....	Roger Denne'e
Turf Technician [Field Maintenance Coordinator]	Bob O'Connor
RVF E-Mail.....	rivervalleyflyers@yahoo.com



From the President: As we approach the end of 2019 and head into 2020, I want to wish everyone health, wealth, and happiness in the New Year. I hope everyone had a great Christmas in 2019, and that 2020 will be a safe and prosperous New Year for everyone.

The indoor flying is now the main club event of the winter season. With all the cold and snowy weather that we have had this fall and early winter, it was hard to get outside to the club field to do any flying, although I know a few who braved the weather and were out. With the short days and low sun angle this time of year, it can be challenging on a cloudy day to see what attitude the aircraft is in when flying outdoors, and I personally have the most trouble seeing what attitude my aircraft is in flying outside this time of the year. That is why the indoor flying is so nice, because it is in a well-lit contained area and the fingers don't freeze when flying. I do like the chance to get something in the air during the long winter season, as the practice keeps my flying skills up until the spring returns. So, come down to the East Junior High gym on Fridays and check it out. See the attached schedule of flying dates in this newsletter.

With winter here and the outside temperature to numbing cold to go out anyway, I hope that everyone has some type of winter project to keep them interested in the hobby during the cold of winter. This could be either repairing or building (buying) something new. So far, I have inspected and done repair on about a third of my aircraft fleet this fall from the summer flying season, and still need to go through the rest of them in the months ahead. This is a good time to do that, and it is amazing the things you will find that will prevent problems when you use them as the weather warms again toward spring. I have not decided if I will build (or buy) a new aircraft yet in 2020.

Just a reminder, we WILL NOT have a January club meeting or a March meeting in 2020, but will have a meeting in February and April. That's all I have this month, so I'll see you next at the indoor flying in January.

Don

Remaining Indoor Flying 2019-2020

Indoor flying continues, and the weather will be the same from event to event. Here is the Indoor Flying schedule remaining for the 2019-2020 season.

January. 3, 10, 24, 2020

February. 7, 21, 28, 2020

March. 13, 20, 2020

April 3, 2020

It will again be at the East Jr. High School field house in Wisconsin Rapids from 7PM-10:30PM. Same as last year.


Roger Denne'e

Understanding Washout

Written by David Andersen

Understanding the twist in your wing

Washout is a design characteristic built into the wing, where the angle of attack is reduced span-wise from root to tip, typically 1° to 2° . The reduction creates a situation where the root of the wing stalls before the tip, softening the stall and allowing the ailerons to be functional deep in the stall.



TYPICAL WASHOUT ANGLES FOR A WW2 FIGHTER MODEL

Washout is a twist in a wing that causes the wingtip to meet the airflow at a lower angle than the root in normal upright flight. Some airplanes don't need it; some airplanes can't fly without it.

Why It Happens

Washout causes the root of the wing to stall before the wingtips stall. The subsequent loss of lift in the root area gently lowers the nose or prevents it from rising farther, keeping the entire wing from suddenly stalling and provoking an unwanted snap roll. Stalls do not always occur at low airspeeds.

Pylon racers, for example, can stall in high G turns, sometimes with disastrous results. At high angles of attack, ailerons become less effective because they are both lifting; the difference in lift becomes less with increasing the angle of attack. Washout causes the ailerons to meet the air at a lower angle. This improves aileron effectiveness at all attitudes, especially at low airspeeds. In a banked turn, the down-aileron increases lift and drag, while the up aileron reduces lift and drag. The difference in wingtip drag

tends to yaw the airplane in the opposite direction of the turn. This is known as adverse yaw.



The author's Howard Pete has washout in only the last rib bay—enough for a nearly constant chord wing

Washout tends to reduce the effects of adverse yaw, but only in the portions of the ailerons that are close to the zero angle of attack.

Some airplanes are trimmed so there is less down-aileron travel than up travel (aileron differential). But aileron differential is a partial cure.

Other designs include engine offset—a remedy that causes problems elsewhere. The best solution is for the pilot to counteract adverse yaw with rudder, even when flying inverted. The result is a coordinated turn.

At high angles of attack, such as in a climbing turn, there is the danger that the down aileron, (left aileron in a right bank) can provoke a stall in that wingtip. Such a stall creates plenty of drag in the wingtip, pulling it back and yawing the airplane in the opposite direction of the turn. If the airplane has significant dihedral, a roll in the opposite direction also develops. This phenomenon is called aileron reversal or aileron snatch.



The glider-like wing of the author's 114-inch span Focke-Wulf Ta 152H requires washout for stability. The aircraft would be uncontrollable without it.

Unfortunately, a pilot's instinct to apply additional aileron deflection makes matters worse. The remedy is to correct with rudder, not more aileron. Beware of this when flying your warbird in an inverted climbing turn or victory roll.

Wingtip vortex is the tendency of the high-pressure air under the wing to curl around the wingtip and cancel the low-pressure air above the wing. This further reduces aileron effectiveness.

It also increases wingtip drag and must be controlled by the vertical stabilizer.

Washout reduces wingtip vortex and its associated drag.

Although wing efficiency is generally unimportant in model aircraft, the reduction of wingtip drag via washout improves lateral (yaw) stability. This is especially important at low speeds and high angles of attack.

Washout, therefore, improves lateral stability and rudder effectiveness.

Wingtip vortices cannot be eliminated, so ailerons are not effective at the tip of the wing. For this reason, in addition to the aileron reversal problem, ailerons rarely go all the way to the wingtip.

In highly swept wings, the washed-out wingtips act as horizontal stabilizers, increasing pitch stability.

When carried far enough, it is possible to eliminate the tail. Some flying wings, such

as the Northrup N-9M, are based on this principle.



The author's 1/3-scale Grumman Lynx has a constant chord wing with no washout. It instead uses Hoerner wingtips and stall strips, which are effective.

Why Not?

Too much of a good thing can cause problems. All the good that washout does in upright flight can be detrimental in inverted flight—such as loss of aileron effectiveness, nonuniform roll rate, adverse yaw, surprise snap rolls, and aileron reversal. For these reasons, washout is rarely used in full-scale aerobatic aircraft. For these aircraft, it is important for the airplanes to behave in inverted flight as closely to upright flight as possible. In addition, aerobatic aircraft need to be predictably snap-rolled.


Constant-chord wings, such as those found on the J-3 Cub or STOL (short takeoff and landing) aircraft, benefit least from washout. They are built to maximize wing area and need all the lift they can get. Instead of washout, they may use stall strips to soften the stall, and shaped wingtips to reduce wingtip vortices in lieu of washout.

Typically, biplanes have their wing incidences adjusted so that the forward wing (typically the top wing in a Stearman or the bottom wing in a Beech Staggerwing) will stall before the rear wing. The ailerons are usually in the rear wing so good aileron control is maintained even if the other wing is stalled.

This is one of the advantages of biplanes over monoplanes; usually this configuration does not merit washout.

LE slats can also prevent tip stalls, but slats are usually combined with washout for an extra margin of low-speed control.

Flaps increase the angle of attack of the wing in the flap area by rotating the chord line. Flaps also increase washout.



In case of engine failure, washout provides good yaw control in Greg Hahn's B-17.

This improves pitch stability and aileron control at low airspeeds.

Models without ailerons steer with rudder and use the dihedral of the wings for banking. As the rudder yaws one wingtip forward, the angle of attack is increased, while the other wingtip decreases its angle of attack.

Washout would partially defeat this effect, so it is seldom used in aircraft of this type, except in Scale models with pointy wings. Washout should be avoided in lightweight wings that are not stiff enough to resist further twisting in flight.

Imagine such a wing in a dive. The root is creating positive lift while the wingtip is generating negative lift because of washout. This twisting force tends to further increase washout if the wing is not stiff enough to resist it.

As speed increases, drag increases, but net lift becomes zero and vertical dive equilibrium develops. If there is enough elevator to pull the nose up, the washout will suddenly reverse and the entire wing will be

lifted, possibly breaking it. If there is not enough airflow over the elevator to pull out, the airplane will plummet to the ground. Many RC gliders have crashed because of this principle.



There's no washout and no incidence in Dave Deschenes' Wildcat—typical of constant-chord dive bombers.

How Much?

The optimum amount of washout varies from zero to several degrees, depending on the following factors:

- High aspect ratio (span/chord) wings need more washout because their thin wingtips tend to stall.
- Tapered wings need more washout in proportion to the amount of taper.
- High wing loading requires more washout because it is prone to tip stalls.
- Underpowered aircraft need more because they must fly at higher angles of attack.



Despite its thin, pointed wingtips, Dave Szabo's Spitfire has excellent handling in part because of 2.5° of washout—roughly the same as the full-scale Spitfire. A low pass before a chandelle is shown here.

- Thin wings need more washout because they abruptly stall at low angles of attack.
- Multiengine airplanes need plenty of washout for rudder effectiveness in case of engine failure.
- Biplanes need less (see the previous “Why Not?” section).
- Aerobatic airplanes need none to be symmetric in flight.
- Washout becomes less effective as dihedral increases.

For Scale models, use the amount of washout used in the full-scale aircraft. In general, RC warbirds use roughly 1° or 2° of washout, adjusted up or down by the aforementioned factors. An RC airplane rarely needs more than 4° of washout.



A 90° sharp-edge stall strip is added to the LE of the Grumman Lynx to lower the stall angle in the root area of the wing. This alternative to washout also works when inverted.

Where?

In most cases, the angle of wingtip attack should be close to zero in level flight, generating little or no lift in level cruise position, so the washout angle equals the root angle. Washout typically is distributed uniformly from root to tip, but not always. Consider the following exceptions:

- The three-piece wings of the Mitsubishi Ki-15 Babs, North American AT-6, and the Junkers Ju 87 Stuka have no twist in their center sections, but begin outboard of the landing gear.

- The Focke-Wulf Ta 152H high-altitude fighter's high aspect ratio wing has 2° of washout, all of it in the aileron area.



Washout can be added after construction by slightly raising both ailerons. This is recommended for the maiden flights of a new model.

- For some models, such as the nearly constant chord Howard Pete, little washout, if any, is needed. But a small amount is included in the wingtips by shaping the LE of the outermost rib bay.

There are several methods of adding washout during assembly, such as temporary tabs on each rib to hold it at the required angle, shims of varying heights supporting the spars, tapered, full-span sticks upon which the ribs rest during assembly, and setting twist after assembly.



Leo Spychalla's Zirol Stuka has a gentle stall despite its pointed wings. The wings have 4° of washout, starting outboard of the landing gear.

Sometimes the ribs and spars can be assembled on a flat surface without washout. The TE of the end ribs are then raised, twisting before the sheeting is applied.

Open-structure wings can sometimes be completely built and covered with heat-shrink plastic film.

The wing is then twisted while heat is reapplied with a hot-air gun.

What if you forgot to build in enough washout, or flight tests suggest it needs more? You might want to play it safe and temporarily include extra washout during those first few flights.



Washout in the Howard Pete's wingtip is formed by shaping the LE in the outer rib bay.

Unless the airplane has full-span ailerons, washout can be increased 1° by slightly raising the TE of both ailerons.

For a typical Giant Scale model, this is less than 3/16 inch. Later, if stalls and tight turns are acceptable, lower the ailerons in small increments until they are back to neutral.

2020 RVF Club Membership Renewal

It's time to renew your club membership for 2020 if you haven't already done so.

Club membership runs from January 1st through December 31st of each year, and getting your renewal in early will avoid a lapse in membership. Memberships may be renewed at our monthly meetings or mailed to our club treasurer. See attached form in this newsletter.

Upcoming Area Events

1/19/2020 Green Bay Wisconsin

Green Bay Model Airplane Club Swap meet and Auction. 8 am to 12 Noon. Admission \$5, 12 & under-free. No table fees. Nice raffle prizes. New location! Gatherings 43 (S of Green Bay on I-43) Exit 171 to Denmark. Turn right at the roundabout after Kwik Trip. Go one block then turn left on the left. (This is a new building so there is no address yet) Depere Rd, Denmark, WI, 54208 (44.345663, -87.839274) Contact Steve Doubek at Email stevedoubek@yahoo.com

01/26/2020 West Bend Wisconsin

Milwaukee Association of R/C Clubs Swap Meet and Auction.

Swap Meet 9 a.m. till 2 p.m. \$5 entry fee, all tables are \$20. For table reservations call Laurie @ 414-315-7229. Scott Jones contact 414-315-7729 or e-mail onehobby@happyhobby.com

Site: 3000 Pleasant Valley RD. West Bend Wi. 53095

March

03/01/2020 Kaukauna Wisconsin

V.A.M. Swap Meet/Auction

NEW VENUE! Doors open at 7:30 sharp.

No early entry. Admission 45. No table reservations. Food & drinks available.

Raffle. Auction starts at 11:30. Visit

www.flyvam.com or email

flyvam670@gmail.com

W2091 County Road JJ, Kaukauna, WI, 54130 (44.315228, -88.29228)

River Valley Flyers Monthly Meeting Notice:

There will not be a monthly meeting in January 2020!!!!

ALSO NOTE!!!!

With winter here, will not have a January or March 2020 monthly meeting.

We will have a February monthly meeting and resume the normal meeting schedule in April.

River Valley Flyers Model Aircraft Club

2020 Membership Form

The “River Valley Flyers” are a model aircraft flying group interested in all aspects of Model Aviation and are located in Central Wisconsin. We are a chartered Academy of Model Aeronautics [AMA] club. All club members must also be AMA Members. We maintain a flying site in southern Portage County in the Township of Grant in the Central Wisconsin area.

Membership Categories and Dues

Full Adult Membership.... \$40

Age eighteen years and older by January 1st of the year of application. Includes voting rights and club field usage rights.

Family/Group Membership.... \$45

All members covered by a Family/Group Membership must have a direct spouse or offspring relationship, Father-Son, Husband –Wife and or Junior Member. Includes voting rights [except for junior members] and club field usage rights.

Junior Membership.... \$15

Under age eighteen years old by January 1st of year of application. All junior members need to be sponsored by a Full Adult Member even though they are not related by an offspring relationship. Includes field usage rights but no voting rights.

Guest Membership.... \$20 For someone who belongs to another local club but wishes to access our field for flying as well. Includes field usage rights but no voting rights. Must send a copy of current AMA and Local Club Membership Cards with application.

MEMBERSHIP APPLICATION (PLEASE PRINT CLEARLY)

Please bring completed application form below with proof of AMA to RVF meeting or mail to:

Bob O'Connor 2220 Lovewood Drive Wisconsin Rapids Wisconsin 54494

Make checks payable to **River Valley Flyers** (Only Cash or Check Accepted)

Name: _____

Address: _____

City: _____ Zip: _____

Phone: _____ E-Mail _____

AMA# _____ Membership Category: _____

Dues Enclosed: _____ (Cash or Check Only)